

Report Date 12/17/2007

Company AHI Home Inspection

Customer

Address

Site Address

Thermographer Al Shah

Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:12:17 02:46:07	
Image Name	IR_0001.jpg	
Emissivity	0.96	
Reflected Temperature	68.0 °F	
Object Distance	6.6 ft	

Description
Master Bedroom East and South walls show signs of air infiltration and poor joints at Vapour barrier