

**Report Date** 12/17/2007

**Company** AHI Home Inspection

**Customer**

**Address**

**Site Address**

**Thermographer** Al Shah

**Contact Person**




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2007:12:17 02:48:53	
Image Name	IR_0004.jpg	
Emissivity	0.96	
Reflected Temperature	68.0 °F	
Object Distance	6.6 ft	

Description
Front Bedroom. Air infiltration,insulation problems